



A.S.K. Enterprise, Inc.
812 56th Street
West Des Moines,
IA 50266
Phone: 515.229.6734

Vinyl/Mesh Repair Instructions

1. Remove all loose ends or rough edges from tear and if possible make sure torn surface is flat.
2. Remove all dirt, grease and moisture from surfaces.
3. Clean surface with alcohol wipes and let surface dry thoroughly.
4. Cut mesh patch 1” larger in width and length than the rip or tear. (avoid square corners on patch) (NOT ALL REPAIRS NEED THE ADDITIONAL MESH IF THE MATERIAL IS JUST CUT VS. MISSING AN AREA)
5. Cut TEAR-AID PATCH at least 1-2" larger than the mesh patch. WILL NEED TWO PIECES! ONE FOR THE INSIDE OF THE DEFECT AND ONE FOR THE OUTSIDE.
6. Apply patch to torn surface avoiding wrinkles or bubbles in surfaces. YOU WILL NEED TO APPLY TEAR-AID PATCH TO BOTH SURFACES OF THE DEFECT. NEED TO OPEN FOAM ENCLOSURE TO APPLY ON INSIDE OF DEFECT AND APPLY OVER THE MESH PATCH IF NEEDED
7. Rub all edges to seal. Rub entire patch aggressively.
Repair is complete.